Walkover Radiological Survey Report

Fort McClellan Calhoun County, Alabama

Prepared for:

U.S. Army Corps of Engineers, Mobile District 109 St. Joseph Street Mobile, Alabama 36602

Prepared by:

IT Corporation 312 Directors Drive Knoxville, Tennessee 37923

Task Order CK10
Contract No. DACA21-96-D-0018
IT Project No. 796887

October 2002

Revision 0

Table of Contents _____

			Page
List o	f Tabl	les	ii
List o	f Figu	ıres	ii
1.0	Intro	oduction	1
2.0	Com	pletion of Radiological Survey at Rideout Field	1
	2.1	Survey Area	1
	2.2	Survey Control	2
	2.3	Radiological Surveys	2
	2.4	Anomaly Verification	3
	2.5	Data Processing	3
	2.6	Results	4
	2.7	Conclusions	4
3.0	Inve	stigation of Radioactive Anomalies	5
	3.1	Selection of Radioactive Anomalies.	5
-	3.2	Investigative Method	5
	3.3	Data Processing	6
	3.4	Results	7
	3.5	Conclusions	7

List of Tables_____

Table	Title		Follows Page	
1	Pelham Range Anomalies		7	

List of Figures_____

Figure	Title	Follows Page	
1	Rideout Field Anomaly	1	
2	Pelham Range Anomalies	1	
3	Main Post Anomalies	1	
4	Main Post Reference Area	3	
5	Rideout Field Radiological Survey	3	
6	Rideout Field Radiological Survey, Pelham Range (Reference Gri-	d) 3	
7	Radiological Survey, Main Post (Reference Grid)	3	
8	Pelham Range Anomalies and Reference Area	6	
9	Main Post Anomaly and Reference Area	6	



1.0 Introduction

IT conducted an airborne radiological survey in October 2001, over selected areas on the Main 3 Post and Pelham Range at Fort McClellan in Calhoun County, Alabama. The survey used an 4 array of detectors to measure the gamma emitting radioactive materials in the soil. During the 5 airborne survey, several areas of elevated radioactivity (i.e., anomalies), shown on Figures 1 and 6 2, were identified at Pelham Range. Two of the identified anomalies (P1 and P2 on Figure 1, 7 Rideout Field) were a radioactive waste disposal site undergoing remediation. This site contained 8 9 cesium 137 (Cs-137) and cobalt 60 (Co-60) sources that had been used in training exercises. Remediation of this area has since been completed and the remediation contractor performed a 10 final status survey. However, radiation "shine" from the uncovered waste masked the area 11 surrounding the remediation site so that it could not be properly characterized during the airborne 12 survey. The area included in the final status survey at Rideout Field is also shown in Figure 1. 13 The other Pelham Range anomalies (P3 through P10) are areas where the elevated counts could 14 not be definitely attributable to naturally occurring radioactive materials. Two anomalies were 15 16 identified at the Main Post (M1 and M2) and one of these has subsequently been investigated (M1). The anomalies at the Main Post are shown on Figure 3. 17

¹8

20 21 IT conducted further investigations on August 26 through 29, 2002, to complete the survey of the area surrounding the Rideout Field anomalies and to determine the nature of the radiological anomalies at Pelham Range and the one on the Main Post. The methods used to complete these investigations and the results are presented in the following sections.

23

22

2.0 Completion of Radiological Survey at Rideout Field

25 26

27

28


24


This section describes the survey area and the field procedures and instruments used to complete the radiological investigation at Rideout Field, including survey area and control, data acquisition, and field verification of radiological anomalies identified during the course of this survey.

293031

2.1 Survey Area

- One area that contained anomalies (P1 and P2) identified during the airborne survey was a
- 33 radioactive waste disposal site that was undergoing remediation (Rideout Field). The
- 34 remediation contractor has since completed remediation and has performed a final status survey









FIGURE 2

PELHAM RANGE ANOMALIES PELHAM RANGE FORT McCLELLAN

AIRBORNE TOTAL EXPOSURE RATE DATA


U.S. ARMY CORPS OF ENGINEERS MOBILE DISTRICT FORT McCLELLAN CALHOUN COUNTY, ALABAMA Contract No. DACA21-96-D-0018





Main Post








FIGURE 3

MAIN POST ANOMALIES MAIN POST FORT McCLELLAN

AIRBORNE LOW ENERGY/HIGH ENERGY RATIO DATA

U.S. ARMY CORPS OF ENGINEERS MOBILE DISTRICT FORT McCLELLAN CALHOUN COUNTY, ALABAMA Contract No. DACA21-96-D-0018



- to document that the site should be released from radiological controls. When the final status
- 2 survey boundary is superimposed on the airborne survey map (Figure 1), it can be seen that the
- area containing the apparent anomalies is larger than the area remediated and included in the
- 4 final status survey. This is expected due to "shine" from the radioactive sources uncovered
- 5 during remediation of the site. In order to complete the radiological characterization of Rideout
- 6 Field, a survey was performed outside the final status survey boundary and extending beyond the
- area affected by shine from the radioactive sources. The survey area is also shown on Figure 1.

8

2.2 Survey Control

- 10 Prior to conducting the radiological survey, the boundary of the proposed survey area was
- located and marked using caution tape. A Trimble GPS Pathfinder® Pro XR unit was coupled to
- the radiological detector during data collection and provided the spatial control required for the
- investigation. GPS data were collected using the Alabama East State Plane Coordinate System,
- North American Datum 1983 (NAD83). In order to provide reasonable line of sight navigation
- during the radiological data collection, marks were made on the ground using surveyor's paint
- down the line the surveyor walked during the data collection process. Paint marks were placed
- along the outside edge of the Ludlum 2221 rate meter detector swath in order to provide
- alignment for the adjacent survey line. A known surveyed location (monitor well) was used to
- 19 check GPS accuracy daily.

20 21

2.3 Radiological Surveys

- 22 The radiation detection system used during the investigation consisted of a Ludlum 2221
- scaler/ratemeter with a Ludlum 44-10 2" x 2" sodium iodide (NaI) detector sensitive to gamma
- radiation. Prior to collecting radiological data, the Ludlum 2221/44-10 instruments were
- background and response checked using a known source and the readings recorded in a logbook.

26

- 27 The Ludlum 2221/44-10 was then coupled with a Trimble GPS Pathfinder® Pro XR unit so that
- 28 the data from the rate meter were logged in real-time by the GPS data logger. The survey was
- 29 performed by holding the detector close to the ground surface and swinging the detector in a "S"-
- 30 shaped pattern while walking at approximately 0.5 meters per second (m/s). One member of the
- 31 survey team followed the operator with surveyor's paint and made marks on the ground to
- 32 provide visual indicators of the survey path.

33

- Prior to beginning the survey of the Rideout Field anomalies, a reference area (approximately 10
- meters by 10 meters) within the boundary of the final status survey was selected and surveyed

- using the methods described above (see Figure 1). This reference area was selected because of
- 2 similar geological makeup to the survey area. In addition, a final status survey has been
- 3 completed in this area in support of license termination; therefore, survey results in this area
- 4 should represent acceptable radiation levels for Rideout Field. An additional reference area was
- 5 surveyed in an unimpacted area at Main Post (Figure 4). This area was selected to provide data
- 6 for comparison to surveys conducted at the Main Post where the geological makeup of the soils
- 7 is different from the soils at the Rideout Field area of Pelham Range. This reference area was at
- 8 the intersection of Diamond Drive and Realm Street.

9

- The survey data were collected at 1-second intervals (approximately 0.5- to 1.0- meter (m)
- intervals) along roughly north-south (N-S) oriented survey lines spaced approximately 1 meter
- apart for most of the survey area. Data were collected in random directions in areas that were
- less accessible due to either thick brush or tree cover. The survey data were downloaded to a
- laptop computer at midday and at day's end to verify that the data were recorded properly and
- that there were no data gaps in the survey coverage. The survey data were backed up on compact
- disc (CD) and are retained in project files.

17

18

2.4 Anomaly Verification

- 19 Following the field survey, preliminary color-contour maps of the radiological data were
- 20 generated and field-checked. Anomalies caused by topographic features (e.g., gullies) were
- 21 labeled as such on the field data maps.


2223

2.5 Data Processing

- 24 Contour maps of radiological data were generated using OASIS Montai® data processing and
- 25 analysis system from Geosoft, Inc. These maps were color-enhanced to aid with interpreting
- subtle anomalies. Select contour maps are presented as Figures 5 through 7.

27

- A series of data processing steps were required to generate the contour maps of radiological data.
- 29 Initially, field positional and radiological data were downloaded from the TDC1 GPS data logger
- 30 to a laptop computer using Trimble Pathfinder® Office. Using Trimble Pathfinder® Office, the
- data were exported in an ASCII-format. GPS base station data provided by Intergraph
- 32 Corporation were used to differentially correct the positional data. Preliminary data processing
- included assessing the ASCII-format data files for correct line and station ranges, removing
- unwanted characters and incomplete data records, and assessing overall data quality. Data file
- names were recorded on data file tracking forms.



LEGEND

UNIMPROVED ROADS AND PARKING

PAVED ROADS AND PARKING

CONCRETE PAD

TREES



REFERENCE AREA

MANMADE SURFACE DRAINAGE FEATURE





UTILITY POLE

FIGURE 4 MAIN POST REFERENCE AREA

U. S. ARMY CORPS OF ENGINEERS MOBILE DISTRICT FORT McCLELLAN CALHOUN COUNTY, ALABAMA Contract No. DACA21-96-D-0018










FIGURE 6

PELHAM RANGE (Reference Grid) FORT McCLELLAN


TOTAL COUNT MAP

U.S. ARMY CORPS OF ENGINEERS MOBILE DISTRICT FORT McCLELLAN CALHOUN COUNTY, ALABAMA Contract No. DACA21-96-D-0018



NAME:	DATE:	
Nicholas Muloshi	September 11, 2001	
PROJECT NUMBER 796887	LOCATION: c:\ITprojects\ftmc\pelhamRF.map	

Coordinate system is NAD83, Alabama East State Plane Note:






FIGURE 7

RADIOLOGICAL SURVEY MAIN POST (Reference Grid) FORT McCLELLAN

TOTAL COUNT MAP

U.S. ARMY CORPS OF ENGINEERS MOBILE DISTRICT FORT McCLELLAN CALHOUN COUNTY, ALABAMA Contract No. DACA21-96-D-0018



Coordinate system is NAD83, Alabama East State Plane Note:



Final, edited ASCII-format data files containing Alabama East State Plane, NAD83 coordinates (X, Y) and the radiological measurement (Z) were converted to OASIS Montaj® format and 3 imported into the data processing and analysis software. Data in the OASIS Montaj® database 4 were reviewed in profile form to verify completeness of data editing. Since two detectors were 5 used for surveying, the count rates were adjusted to a common base level. This correction was 6 determined from the source check and reference grid data. The data were then gridded with the 7 minimum curvature gridding module using an Akima spline. The grid cell size for the 8 radiological data was chosen to be 0.30 meters. A color contouring scale was selected to 9 enhance data anomalies of interest to this investigation. The names of files generated and 10 processing parameters used were recorded on data processing forms. Final processed map names 11 are shown in the data processing box found in the lower left corner of each contour map 12 presented. The processed radiological data and the completed radiological data quality control 13

15 16

:18

21

14

1

2.6 Results

forms are retained in project files.

Results of the surveys conducted at Rideout Field and the two reference areas are found on 17 Figures 5 through 7. Results for the survey area are within expected ranges for the type of soil at Pelham Range. These results are comparable to the results measured for the Rideout Field and 19 Main Post reference areas. Anomalies identified during the course of this survey can be 20 attributed to the makeup of the soils and the geometry of the measurement. For example, clay soils typically have a higher natural radiation background than sandy soils. Surveys performed 22 in a gully will be higher for a given soil type since the detector is surrounded by the source 23 material thus allowing more of the gamma rays to interact in the detector resulting in a higher 24 count rate. These anomalies are identified on Figure 5 as either a gully or gravel road. Blank 25 spaces on the survey map represent areas than were inaccessible due to obstructions such as 26 concrete pillars, army tanks, or dense brush. There is no indication that radiological anomalies 27 exist in these inaccessible areas (i.e., no elevated counts near these areas). 28

29 30

31

32

33

34

35

2.7 Conclusions

The radiological investigation at Rideout Field was completed by performing a walkover survey using a Ludlum 2221/44-10 gamma scintillation detector. Accessible areas outside the boundary of the final status survey and extending into the area unaffected by radiation shine from the waste disposal site were surveyed. Survey results were within the expected range for naturally occurring radioactive materials in soil. Anomalies identified during the course of the survey

were due to variability in soil types and measurement conditions (i.e., geometry). There is no

2 indication that radiological anomalies were present in inaccessible areas.

3

1

3.0 Investigation of Radioactive Anomalies

5

This section describes the selection and location of radioactive anomalies identified from the results of the airborne survey and the methods used for investigation.

8

12

7

3.1 Selection of Radioactive Anomalies

Radioactive anomalies were identified from the results of the airborne survey at Pelham Range

and Main Post. Two of the anomalies at Pelham Range were due to the ongoing remediation of a

radioactive waste site during the course of the survey. The remediation contractor has since

completed remediation and has performed a final status survey of the affected area. Eight

anomalies at Pelham Range (P3 through P10) were selected for further investigation based on

elevated exposure rates measured during the airborne survey and on historical land use (see

16 Figures 1 and 2).

17

15

18 Two anomalies at the Main Post (M1 and M2) were selected for further investigation (Figure 3)

based on the results of the airborne survey. One of these was selected because of the presence of

20 elevated counts in the Cs-137 region and the other was selected because of an elevated Low-

21 E:High-E ratio. The Low-E:High-E ratio is an analysis tool used to help identify potential

locations of man-made radiation since the low-energy portion of the spectrum contains the

energy from the man-made sources of interest and the high-energy portion of the spectrum is

24 dominated by natural radiation.

2526

22

23

IT investigated the Cs-137 anomaly (M1) on February 1, 2002 using a Ludlum Model 19 microR

27 meter and a Ludlum 2221 with a Ludlum 44-10 NaI detector. Subsequent sampling and gamma

spectroscopy analysis confirmed the presence of Cs-137.

29 30

3.2 Investigative Method

31 The radioactive anomalies on the Main Post and Pelham Range were investigated using an

32 Exploranium Gr-135 Identifier portable gamma spectrometer. The GR-135 is used to search for,

33 locate, and identify gamma-emitting radioactive materials. The instrument contains a 4 cubic

34 inch NaI detector and associated analysis software for identification of radioactive material using

35 the built in gamma-ray library.

1

2 The GR-135 was stabilized each morning prior to use and again at the end of each day. The

3 instrument was stabilized by placing it in the docking station that contained a small Cs-137 check

source. Stabilization "fine-tunes" the system by adjusting the internal gain and aligning the

5 spectrometer with the Cs-137 peak.

6

4

7 Reference spectra were collected at the Rideout Field and the Main Post Reference areas (Figures

8 and 9). These spectra were used for comparison to the spectra collected at the Pelham Range

and Main Post anomalies, respectively.

9 10 11

13

8

Each anomaly was located and staked using the coordinates from the airborne survey. Initially,

the area around each stake was surveyed with a Ludlum 2221/44-10 NaI detector (as described in

Section 2.3) to identify the area in the vicinity of the anomaly with the highest count rate. After

the highest count rate area was identified, the portable gamma spectrometer was used to identify

the radiological contaminants at the location by placing the instrument on the ground and

16 collecting a spectrum for 30 minutes. The GR-135 was used in the "Identify" mode. In this

mode the instrument collects a spectrum for the preset time and, at the conclusion of the count,

automatically performs spectrum analysis to identify the nuclides in the spectrum based on the

19 reference library. The spectrum analysis indicates the nuclide type (i.e. Industrial, Special

Nuclear Material, or Medical), isotope, and relative size for each identified nuclide. Each

spectrum collected was stored for download to a PC.

2223

24

25

26

27

21

18

In addition to the spectrometer measurements, exposure rate measurements were made at the

ground surface and at 1 meter above ground surface using a microR meter. Gamma spectrometer

and exposure rate readings were also collected within the final status survey reference area and

the Main Post reference area. The gamma spectroscopy measurement locations were marked

with surveyor's paint unless the highest reading was found at the location of the stake.

28 29

31

33

3.3 Data Processing

30 Spectra collected in the reference areas and at each of the anomalies were downloaded to a PC

using the Exploranium Identiview software. The spectra were also converted to a text file and

imported to an Excel spreadsheet for inspection and graphical presentation of the data. Use of

the Identiview software and Excel enabled the data from the reference areas to be viewed with

the anomalies for direct comparison of the spectra.

35

:34

Figure 8
Pelham Range Anomalies and Reference Area
Pelham Range
Fort McClellan





Figure 9
Main Post Anomaly and Reference Area
Main Post
Fort McClellan



3.4 Results

- 2 Gamma spectra collected at the eight Pelham Range anomalies and the Rideout Field reference
- area are shown on Figure 8. The only nuclides identified in these spectra were naturally
- 4 occurring uranium series radionuclides (Pb-214, Bi-214) and potassium 40 (K-40). In some
- 5 cases, the elevated exposure rates were attributable to visible shale outcroppings or clayey soil.
- 6 Surface exposure rates ranged from 8 microroentgens per hour (µR/hr) for the reference area to
- 7 42 μR/hr at Anomaly P4. Relevant comments regarding the Pelham Range anomalies are
- 8 provided in Table 1.

9

1

- 10 As mentioned previously, the Main Post Anomaly was selected from the results of the airborne
- survey because of a high Low-E:High-E ratio. A spectrum was collected at the Main Post
- 12 Anomaly on August 27. This anomaly is located on a topographic high and had a low exposure
- rate. No elevated count rate areas were found in the vicinity of the stake that marked the
- anomaly therefore the measurement was made at the stake. Upon completion of the count, the
- GR-135 identified Cs-137 in the spectrum. There was some concern that the apparent Cs-137
- peak had been misidentified due to thermal drift of the detector (i.e., that the 609 keV Bi-214
- peak had been identified as the 662 keV Cs-137 peak). A decision was made to repeat the
- measurement on August 28 after stabilization of the instrument.

19

- 20 A spectrum was collected at the same location (Main Post Anomaly) during the morning of
- 21 August 28. No nuclides were identified in this spectrum. A spectrum was also collected at the
- 22 Main Post Reference Area on August 28.

23 24

3.5 Conclusions

- 25 Eight Pelham Range anomalies were investigated due to elevated exposure rates determined
- 26 during the airborne survey and based on historical use of the site. The investigations were
- 27 conducted using an Exploranium GR-135 portable gamma spectrometer. Only naturally
- occurring radioactive materials (uranium series radionuclides and potassium) were identified in
- 29 any of these spectra. Elevated count rate areas were associated with clayey soil and visible shale
- outcroppings. No further radiological investigation of these anomalies is needed.

31

- 32 The Main Post Anomaly (M2) was selected for further investigation due to a high Low-E:High-E
- ratio. A high ratio for this parameter could be indicative of the presence of man-made radioactive
- materials such as Cs-137 or Co-60. However, the counts in the Co-60 and Cs-137 channels were
- low, as was the total exposure rate; therefore, the high Low-E:High-E ratio was probably an

Pelham Range Anomalies Fort McClellan, Calhoun County, Alabama

Table 1

Anomaly	Surface Exposure	1-meter Exposure	Comments
Number	Rate (μR/hr)	Rate (μR/hr)	
P1	8	8	Anomalies P1 and P2 have been remediated. These measurements were made
P2	8	8	at the Pelham range reference area.
P3	17	13	Visible shale outcropping.
P4	42	21	Extensive shale outcropping. Measurement made on shale.
P5	16	12	Shale outcropping. Readings taken in washout gully.
P6	12	10	Kudzu field.
P7	11	9	Clay.
P8	6.5	5.5	
P9	8	7.5	
P10	8	5	

Measurements were made with a Ludlum Model 19 MicroR meter. $\mu R/hr$ – Microroentgens per hour.

- artifact due to the low natural exposure rate. A higher natural exposure rate would have
- 2 increased the counts in the 609 keV Bi-214 peak and would have masked the low levels of Cs-
- 3 137 that are present in soils due to fallout from nuclear weapons testing. Figure 9 shows the
- 4 spectrum from the Main Post Reference Area and the two spectra collected at the Main Post
- 5 Anomaly M-2. It is concluded that the identification of Cs-137 at the Main Post anomaly was
- due to thermal drift of the detector and/or the low natural exposure rate at that location.
- 7 Regardless of the reason, it can be seen on Figure 9 that the counts in the overall spectrum are
- lower at the anomaly than at the reference area. Therefore, further radiological investigation of
- 9 this anomaly is not recommended.